


**Sidewall Displacement Diffuser (SDD)** 


Page: 1 of 5

SDD ARTS

## SDD WITH MOUNTING TAB ASSEMBLY ▼

## SDD WITH MUD FRAME ASSEMBLY ▼





Item	Description
1	Displacement Flow Recessed Diffuser sub-assembly
2	Long mounting bracketacket
3	Short mounting bracket
4	Mud frame sub-assembly

Page: 2 of 5

# INSTALLATION INSTRUCTIONS

# READ INSTRUCTIONS COMPLETELY BEFORE STARTING INSTALLATION


# **Single Unit - Standard Frame**

- Check the opening to ensure that squareness of the opening is within the tolerance (Figure A). If squareness is not within tolerance than correct opening.
- 2. Drill holes in the mounting brackets as required. The mounting brackets are 1" shorter than the dimension diffuser.
- 3. Install mounting frame into opening with fasteners (supplied by others). Make sure fasteners are secured to a solid base (Figure B).
- 4. Insert SDD into the opening making sure that the mounting clips engage with the mounting brackets. (Figure C and Figure D)

#### FIGURE A

FIGURE C


WALL BY OTHERS -



DIFFERENCE BETWEEN DIAGONALS CANNOT EXCEED 3/16"

#### **FIGURE B**





# ONCE INSTALLED UNIT SHOULD BE FLUSH TO OUTSIDE OF WALL

**SCREWS BY OTHERS** 


Page: 3 of 5

Table 1				
ltem #	Description			
1	Diffuser x 1			
2	Long Mounting Bracket x 2			
3	Short Mounting Bracket x 2			

#### INSTALLATION INSTRUCTIONS


#### **Multiple Units**

- 1. Check the opening to ensure that squareness of the opening is within the tolerance (Figure A). If squareness is not within tolerance then correct opening.
- 2. Drill holes in mounting brackets as required. The mounting brackets are supplied in multiple sections. The O.A. (overall length) of the brackets is 1" shorter than the O.A. dimension of all units.
- 3. Install mounting frames into opening with fasteners (supplied by others). Make sure fasteners are secured to a solid base (Figure B).
- Insert DFR into the opening making sure that the mounting clips engage with the mounting bracket. Repeat for additional DFR's. (Figure D and Figure E)
   NOTE: End mounting brackets are not required between multiple sections.



#### FIGURE D





#### FIGURE E




Table 2			
ltem #	Description		
1	Diffuser x 1	Multiple description qty. by #of sections	
2	Long Mounting Bracket x 2	by not sections	
3	Short Mounting Bracket x 2	2 Onlynly	

Page: 4 of 5

## INSTALLATION INSTRUCTIONS


# SDD with mud frame

- Check the opening to ensure that squareness of the opening is within the tolerance (Figure F). If squareness is not within tolerance then correct opening.
- 2. Install mud frame (supplied mill finish standard) into opening with fasteners (supplied by others). Make sure fasteners are secured to a solid base (Figure H).
- 3. Frame to be finished in place and painted before diffuser is inserted into opening.
- 4. Insert SDD into Opening making sure that the mounting clips engage with the mounting brackets (Figure I).

Table 3			
ltem #	Description		
1	Diffuser x 1		
44	Mud Frame x 1		

# FIGURE F






DIFFERENCE BETWEEN DIAGONALS CANNOT EXCEED 3/16"


#### FIGURE G





#### FIGURE H





# FIGURE I



